Ohio EPA - Daily Discharge Monitoring Report - Form 4500

SUBMISSION ID:

FACILITY:

LOCATION:

COUNTY:

DISTRICT:

142711

American Energy Corp - Century Mine

43521 Mayhugh Hill Rd Twp Hwy 88

Beallsville, OH 43716

Belmont SEDO

STATUS:

Original 01L00091\*GD

PERMIT NUMBER:

STATION CODE: MONITORING PERIOD: REPORTING LAB:

2010-11-01 To: 2010-11-30

ANALYST:

NO DISCHARGE INDICATOR: AL

PARAMETER PARAMETER CODE UNITS	(Mn) 01055		l(	l		((	ñ	ll .
	01033	ii .	<u> </u>	<del> </del>			<u> </u>	<u> </u>
	ug/l			ļ				
FREQUENCY	l / 2 Weeks							
SAMPLING TYPE	Grab		]	ļ		<u>                                     </u>		<u> </u>
2010-11-01	<u></u>	<u> </u>		}		) 		
2010-11-02				<u> </u>		[	ļ	<u> </u>
2010-11-03				ļ				
2010-11-04			ļ	ļ		<u></u>		
2010-11-05				Ļ				
2010-11-06								
2010-11-07				l				
2010-11-08								
2010-11-09				<u> </u>				L
2010-11-10								
2010-11-11								
2010-11-12								
2010-11-13								
2010-11-14								
2010-11-15	**							
2010-11-16					]			
2010-11-17								
2010-11-18								
2010-11-19								
2010-11-20								
2010-11-21								
2010-11-22								
2010-11-23								
2010-11-24								
2010-11-25								<del></del>
2010-11-26								· · · · · · · · · · · · · · · · · · ·
2010-11-27								
2010-11-28				<del></del>				
2010-11-29				<u> </u>				
2010-11-30				<u></u>				<del></del>
Minimum			Property of the Property of th	to the statement	VINTER THOUSE			
Maximum								
Average Count				<u></u>				
Name of Responsible Official	I certify under the pen	alty of law that I have p	ersonally examined and	am familiar	Sig	nature of Responsible	Official or Authorized	
Cody Mozena	with the information submitted herein and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.  Page 8							2010-12- 14 11:12